

Department of Energy

Washington, DC 20585

June 18, 2004

14. 191 In (+ 25 and the second second

The Honorable John T. Conway Chairman Defense Nuclear Facilities Safety Board 625 Indiana Avenue, NW, Suite 700 Washington, DC 20004-2901

Dear Mr. Chairman:

This letter is to inform you that the work has been completed at Richland resolving the weld porosity concerns with some DOE-STD-3013 outer can welds. The re-packaging and welding of 358 DOE STD-3013 outer containers was completed on May 27, 2004.

The need for this effort was delineated in the Assistant Secretary for Environmental Management's February 5, 2003, letter on Commitment 110 of Revision 2 to the *Implementation Plan for Stabilization and Storage of Nuclear Material* (IP 2000-1).

Should you or your staff have any questions concerning these issues, please contact me at (202) 586-0738 or Keith Klein, Manager, Richland Operations Office, at (509) 376-7395.

Sincerely,

fres Triay

Dr. Inés Triay Deputy Chief Operating Officer Environmental Management

cc: M. Whitaker, DR-1/DOE K. Klein, RL/DOE

